

# KDT-M1 100

Duct temperature sensors



	Unit of measurement	KDT-M1 100
Maximum supply voltage	V	5
Ambient air temperature min	°C	-30
Ambient air temperature max	°C	80

## Dimensions

L
100

