

Переход 900/630





	циница черения	Переход 900/630
--	-------------------	-----------------

Размеры

d1	d2	l1	12	L
900	630	100	80	416

